GLebe House On Glebe Farm New Castle, Delaware HABS No. Del- 134

HABS DEL

2- NEWCA

42.

## PHOTOGRAPHS WRITTEN HISTORICAL AND DESCRIPTIVE DATA District of Delaware

Historic American Buildings Survey Weston H. Blake, District Officer 909 West Street, Wilmington, Delaware

HABS DE L

## GLEBE HOUSE On Glebe Farm, New Castle, Delaware

2- NEWCA

Owner: Rector, Wardens and Vestry of Immanuel Church, New Castle, Delaware

Date of Erection:

About 1830

Present Condition: Good. Some modern additions:- chimney on east side, a window and probably the front porch.

Number of Stories: Two and one half, with cellar and small loft under ridge. Lower service wing in rear.

Materials of Construction: Brick. Plastered interior; shingle roof; usual woodwork.

Other Existing Records: Immanuel Church Records; New Castle on the Delaware by WPA Writers Project.

Additional Data: The house has the characteristics of the local buildings of the 1825-35 decade. The north west gable end with its double chimneys with connecting wall, give dignity to the whole house. The large-light windows and and single dormer window on front, the reduced brick cornice with the very slightly projecting roof, and the simple woodwork are characteristics of the date and locality.

The date of the control of the contr

Approved

District Officer